
WIRING INSTRUCTIONS



WIRING SPECIFICATIONS						
Wire No.	Wire Color	Origin or Gauge	Length	Terminals, Connectors and 1 or 2 End Wire Preparation		
1	Black	Cord/14 Ga.	2"	Strip 3/16" For T2.		
2	White	Cord/14 Ga.	2"	Strip 3/16" For T2.		
3	Green	Cord/14Ga.	6-3/4"	Strip 3/16" For T1.		
4	Yellow	16 Ga.	5"	Strip 3/16" For T2/Strip 3/16" For T3.		
5	Black	Field/16 Ga.	See Note	Strip 3/16" for T2.		
6	Yellow	Field/16 Ga.	2-3/4"	Strip 3/16" For T3.		

All leads must be held to ± 1/8". All field leads to be measured from and perpendicular to laminations. All lead lengths are before stripping.

		rg.				
TERMINAL DESCRIPTION						
Code	Part No.	Onty.				
T1	23-74-0841	1				
T2	23-74-0851	4				
ТЗ	23-74-0300	2				
CONNECTOR DESCRIPTION						